

<b>Technical Information</b>	Date: 13.10.2016 Official: Heckl, Michael Department.: ST-FIR/MKP3
------------------------------	--

<b>Tech. Information No.</b>	2044 / 2016
<b>Subject:</b>	LSN 0300 A and LSN 1500 A Module

<b>Short Description:</b>	Problems in loops with TTap
---------------------------	-----------------------------

<b>Hardware</b> <input checked="" type="checkbox"/>	<input type="checkbox"/> Device	<input checked="" type="checkbox"/> Module	<input type="checkbox"/> PCBA
<b>Software</b> <input type="checkbox"/>	<input type="checkbox"/> Application	<input type="checkbox"/> Driver / Extension	<input type="checkbox"/> Firmware

Affected Products (details)	CTN	SAP no.	Aff. version	New version
LSN0300	LSN 0300 A	4.998.137.277	1.0.53	1.0.53
LSN1500	LSN 1500 A	4.998.137.278	1.0.53	1.0.53
FPA-1200-C-APR		F.01U.275.086		

Priority Level	Criterion
I <input type="checkbox"/>	The change has to be made <b>immediately</b> (see dates below)
II <input type="checkbox"/>	The change has to be made during the next inspection.
III <input checked="" type="checkbox"/>	Change might have to be made with new installations.
None <input type="checkbox"/>	General Information (like new tool, new feature, new SW release)


Action Plan	
<input checked="" type="checkbox"/>	Inform customers
<input type="checkbox"/>	Arrange re-work of stock (NSO)
<input type="checkbox"/>	Arrange re-work of stock (customer)
<input type="checkbox"/>	Arrange re-work of installed products
<input checked="" type="checkbox"/>	See detailed actions on following pages

Cause
<p>In some TTap configurations, a line interruption ("open") on the loop can lead to a loss of the function of one or more peripherals on this loop. A trouble message will be indicated for each peripheral.</p>

Action(s)
-----------

Following process shall be applied for new installations:

To avoid losing elements in case of an “open” condition, additional elements need to be installed on the loop. This is shown in the following picture:



The elements shown in green and blue are the additional elements.

*It is important to wire the colored elements exactly as shown in the diagram.*

The blue extra elements must be installed as TTap, which means to connect both the incoming and the outgoing b wire to b1.

The green isolators must be installed so that one b wire is attached to b1 and the other to b2.

The yellow elements (detectors) are mandatory parts of this solution. They must be wired in a TTap (incoming and outgoing b lines attached to b1).

As long as the blue, green, and yellow elements are placed and connected as shown here, the rest of the topology can be chosen at will. Do not insert any other elements in the sequence of the colored elements.

The blue and green elements can be of any LSN element type as long as they are not easily removable. This means that they definitely should not be detectors in sockets. They can be manual call points, sounders, or interface modules.

The LSN-a wire must be connected as always. Incoming and outgoing LSN-a wires are always directly connected to each other.

This solution does not support condition monitoring.

Required Components	Part no.
Attachment(s)	

<b>BU Manager</b>	Knauel, Thomas	<b>Clerk in Charge:</b>	Heckl, Michael
-------------------	----------------	-------------------------	----------------

**Distribution**

Distribution BU FIR	<input checked="" type="checkbox"/> Celebi Guenay (ST-FIR/QMM), Knauel Thomas (ST-FIR/MKP ST-FIR/MKT), Heckl Michael (ST-FIR/MKP3) <input checked="" type="checkbox"/> Angstenberger Josef (ST-FIR/MKR-EU) <input checked="" type="checkbox"/> Lim Yong Gang (ST/SRM-AP), Leonard Hew (ST-FIR/MKR-AP), Quek Daniel (ST-CO/MKR2-AP) <input checked="" type="checkbox"/> Squarize Alex (ST/SRM-LA), Pinto Erik (ST/STS-LA ST-ASA/SRA-LA), Render Chelsea (ST/SRM-NA) <input type="checkbox"/>
Distribution BU IN	<input type="checkbox"/> Hossmann Daniela (ST-IN/MKR-EU), Kugler Gerhard (ST-IN/MKR2-EU), Endres Dirk (ST-IN/QMM) <input type="checkbox"/> Berberian Alexandra (ST-IN/MKR-SEF), Tantry Ananth (ST-IN/MKR-SEM), Karlsson Mathias (ST-IN/MKR-SEN), Rodriguez Herrero Jose Manuel (ST-IN/MKR-SEI), Oppab Maria (ST-IN/MKR-SAN), Malek Michal (ST/MKR-SEP) <input type="checkbox"/> Mechler Tom (ST-IN/MKR-NA) <input type="checkbox"/>
Distribution BU ESS	<input type="checkbox"/> Loh Leon (ST-ESS/MKP1.4), Maier Holger (ST-ESS/MKP1.2), Wings Maarten (ST-ESS/MKP1.3), Redeker Bernd (ST-ESS/QMM), Jan von Rosenstiel (ST-ESS/MKP1.1), Reinhard Bloss (ST-ESS/MKP1) <input type="checkbox"/> Funke Thomas (ST-ESS/ENG) <input type="checkbox"/> Nikolas Mangold-Takao (ST-ESS/MKP1), Jaco Liebetrau (ST-ESS/MKT) <input type="checkbox"/> Markus Brack (ST-ESS/MKP2.3), Huse Istvan (ST/PRM2-EU), Law Jeffrey (ST/PRM1-AP) <input type="checkbox"/> Gary Deng (ST-PRM-CN), James Judson (ST-IN/MKR-NA) <input type="checkbox"/>
Other parties affected	<input checked="" type="checkbox"/> Steidle Kurt (ST-ASA/PRM1) <input checked="" type="checkbox"/> Proyer Konrad (ST-ASA/SRA-EU), Schrimpf Felix (ST-ASA/PRM), Wilson Jim (ST-ASA/SRA-AM), Tan Woo Khiang (ST/ASA-AP) <input checked="" type="checkbox"/> Pedolzky Georg (ST-BT/PRM1) <input type="checkbox"/> <input type="checkbox"/>