

Technical Information						Date: Official: Department:	17.08.2017 Haug ST-FIR/MKP1			
Tech. Information No.			•	2132 / 2017						
Subject:			FLM-420	FLM-420-I8R1-S (CAR 170366)						
Short Description:			have be that cas the affected	At higher operating temperatures the relay of FLM-420-I8R1-S modules which have been delivered in 06/2017 or 07/2017 might not switch as expected. In that case a trouble message will occur at the panel display. For identification of the affected products, please find the attached list with serial numbers. Affected is only the relay functionality, all other functions e.g. input function are working as expected.						
Hardw	2ro [☐ ☐ Devi	20		☐ Module		ПРСВА		
Hardware 🖂							•	+= -		
Software		Арріі	Application		☐ Driver / Extension		☐ Firmware			
Δffecte	ed Produ	cts (det	ails)		CTN	SA		AP no.		
			-	av		FLM-420-I8R1-S		F.01U.033.251		
Octo-input interface modu			idic With rei	le with relay		T LW 420 IOINI 3		010.000.201		
Period of delivery ex-Warehouse from				from:	om: 06/2017			07/2017		
Affected serial numbers					see attache	ed list		to: see attached list		
TOTAL SEC ALLACHEU IIST										
Priority Level Criterion										
1		The change has to be made immediately (see dates below)								
П	\boxtimes	The change has to be made during the next inspection.								
III		Change has to be made, if the error pattern recurs and with new installations.								
None		General Information (like new tool, new feature, new SW release)								
Action	Plan									
\boxtimes	Inform customers									
\boxtimes	Arrange replacement of stock (CSO)									
\boxtimes	Arrange replacement of stock (customer)									
\boxtimes	Arrange replacement of installed products									
\boxtimes	See detailed actions on following pages									
•										
Start Date 17.08			08.2017			Completion D	ate n.a.			



Error(s) and Effect(s)

At higher operating temperatures the relay of the mentioned products might not trigger connected products and a trouble message will occur at the panel display.

Cause

The supplier delivered relays, which are out of specification.

Action(s)

1. Actions to keep deliverability:

Current products on stock are fully tested. The tested units are available for sales or exchange. 100% test in production plant is implemented.

2. Actions to resolve root cause:

Risk assessment and root cause analysis with supplier is ongoing.

3. Replacement of already delivered products:

For products which are already installed:

The replacement has to be made during the next inspection.

The affected products can be identified by serial number, see attached xls-file. Please find the attached description for the details.

If the product is affected, please exchange it via RMA process (standard after sales process). RMA-file is attached.

For products which are still in CSO or customer stock:

2 replacement processes have been installed.

- 1. Customers which have received bigger quantities (see attached xls-file) will be handled by CDC Tilburg.
- 2. Customers which have received smaller quantities (see attached xls-file) will be handled by standard after sales service procedure (RMA process).

Notes

As soon as possible, please inform the customers, mentioned in the xls-file. Please advise them to follow the respective exchange process. The process is described in the chapter "Action(s), 3. Replacement of already delivered products:".

Attachment(s)

20170816_Information_IF-Modules_sh.pptx: Description to identify the affected products 20170816_CAR170366_Customer-Deliveries_sh.xlsx: List of customers which have been delivered 20170725_Affected-Production-Lot-Numbers_IF-Modules.xlsx: List with affected production lot numbers 20170816_RMA-I8R1_all-countries_sh.doc: RMA form to be filled for standard ASA process

BU Manager Thomas Knauel	Clerk in Charge:	Stefan Haug, Bernd Harbers
--------------------------	------------------	----------------------------



Distribution Schlüter Eckhard (ST-FIR/QMM), Ladwig Uwe (ST-FIR/PG, Knauel Thomas (ST-FIR/MKP ST-FIR/MKT), Wendlik Verena (ST-FIR/COR), Haug Christopher (ST-FIR/ENG), Majer Claudia (ST-FIR/QMM), Windisch Tjark (ST-FIR/ENG4), Marier Ronald (ST-Distribution BU FIR FIR/MKP3, Heckl Michael (ST-FIR/MKP3), Harbers Bernd (ST-FIR/MKP1.2) Arabacioglu Kerem (ST-FIR/MKR-EU), Angstenberger Josef (ST-FIR/MKR-EU) \boxtimes \boxtimes Ong Kah Seong (ST-FIR/MKR-AP), Leonard Hew (ST-FIR/MKR-AP), Quek Daniel (ST-CO/MKR2-AP) \boxtimes Paredes Ivan (ST/MKR-LA), Render Chelsea (ST/SRM-NA) Distribution BU ESS \boxtimes Markus Brack (ST-ESS/MKP2.3), Huse Istvan (ST/PRM2-EU) \boxtimes Schrimpf Felix (ST-ASA/PRM) Other parties affected \boxtimes Proyer Konrad (ST-ASA/SRA-EU), Pinto Erik (ST-ASA/SRA-LA) Wilson Jim (ST-ASA/SRA-NA), Tan Woo Khiang (ST-ASA/SRA-AP) \boxtimes Hemke Tobias (ST-ASA/STS3-EU); Gill Manjit (ST-ASA/STS-UK) \boxtimes Schwichtenberg Heiko (ST-IE/PRM2)