

Technical Information	Date: 12.07.2018 Official: Marier Department: BT-FIR/MKP3
------------------------------	---

Tech. Information No.	2134 / 2017
Subject:	FPA-5000 firmware 2.21.2: LSN module fault message on panel

Short Description:	Fault message in combination with LSN module V1.0.53 and true t-tap topology → "Exchange module now! See TI 2134/2017"
---------------------------	--

Hardware <input checked="" type="checkbox"/>	<input type="checkbox"/> Device	<input checked="" type="checkbox"/> Module	<input type="checkbox"/> PCBA
Software <input checked="" type="checkbox"/>	<input type="checkbox"/> Application	<input type="checkbox"/> Driver / Extension	<input checked="" type="checkbox"/> Firmware

Affected Products (details)	CTN	SAP no.	Aff. version	New version
300mA LSN communication module	LSN 0300 A	4.998.137.277	1.0.53	See "Actions"
1500mA LSN communication module	LSN 1500 A	4.998.137.278	1.0.53	See "Actions"
Main Panel Controller	MPC-xxxx-C	All languages	All	See "Actions"
Main Panel Controller	MPC-xxxx-B	All languages	All	See "Actions"
Main Panel Controller	FPA-1200-MPC-C	All languages	All	See "Actions"
Main Panel Controller	FPA-1200-MPC	All languages	All	See "Actions"
Main Panel Controller	FPA-1100-DE	F.01U.316.057	All	See "Actions"

Number of delivered devices	
Period of delivery	from: to:
Affected serial numbers	from: to:

Priority Level	Criterion
I <input type="checkbox"/>	The change has to be made immediately (see dates below)
II <input checked="" type="checkbox"/>	The change has to be made during the next inspection.
III <input type="checkbox"/>	Change has to be made, if the error pattern recurs and with new installations.
None <input type="checkbox"/>	General Information (like new tool, new feature, new SW release)

Action Plan	
<input checked="" type="checkbox"/>	Inform customers
<input type="checkbox"/>	Arrange re-work of stock (CSO)
<input type="checkbox"/>	Arrange re-work of stock (customer)

Print out of this template is not subject of the updating service. Only the version in the Intranet is always up to date.

<input type="checkbox"/>	Arrange re-work of installed products
<input checked="" type="checkbox"/>	See detailed actions on following pages

Start Date	12.07.2018	Completion Date	11.07.2019
-------------------	------------	------------------------	------------

Problem description

In the LSN module firmware V1.0.53 a feature called “detector removal” was implemented for the Hong Kong market.

After market introduction an issue (in some rare cases a loop interruption could lead to a case where several LSN devices are reported missing. A loop restart solved the problem.) was detected in the V1.0.53 firmware affecting only certain t-tap configurations and subsequently a work-around was published (see technical bulletin [TI 2044/2016](#))

Please refer to chapters “Cause” and “Action”.


Cause

The problem is only occurring on LSN bus systems with manually addressed T-Tap topologies (mixed-topology or stub)!


All other LSN bus topologies (e. g. loop, auto-addressed stub) are not affected!

This problem only occurs in systems with LSN module FW V1.0.53!

In RPS the topology tree needs to be like shown in the picture below:





“True T-tap” means that the isolator function of the LSN elements is not used. In T-tap configurations the b-wires of the LSN-bus are only connected to one of the the b-connectors of the devices (e. g. b1). See example (round elements) below:



Action

All customers (except in HK) who use manual addressing of detectors with true T-TAP topologies:
With MPC firmware V2.21.2 we have implemented a check to identify affected installations.

In case you have true T-tap topologies in your system and LSN modules with firmware V1.0.53 you will get a fault message as shown below:



In case your system is affected please provide photos of the fault messages on the MPC screen (similar to above) to ASA referring to TI 2134/2017.

You will then receive a replacement for the affected LSN modules.

For Hong Kong customers:**No return to ASA!**

Please get in contact with Leo Yau (Leo.Yau@cn.bosch.com) who will provide LSN modules with firmware V1.0.55 on demand.

Notes

Download all technical bulletins (TIs) and released software from the '[ST-FIR Tech Support](#)' sharepoint (registered users only)

Required Components**Part no.**

Print out of this template is not subject of the updating service. Only the version in the Intranet is always up to date.

n. a.	

Attachment(s)
TI 2044/2016

BU Manager	Knauel	Clerk in Charge:	Marier
-------------------	--------	-------------------------	--------

Distribution

Distribution BU FIR	<input checked="" type="checkbox"/> Julian Tersteegen (BT-FIR/QMM), Claudia Majer (BT-FIR/QMM), Knauel Thomas (BT-FIR/MKP BT-FIR/MKT), Heckl Michael (BT-FIR/MKP3) <input checked="" type="checkbox"/> Angstenberger Josef (BT-FIR/MKR-EU) <input checked="" type="checkbox"/> Ong Kah Seong (BT-FIR/MKR-AP), Leonard Hew (BT-FIR/MKR-AP) <input checked="" type="checkbox"/> Paredes Ivan (BT/MKR-LA), Miers Christopher (BT/FIR-MKT) <input checked="" type="checkbox"/> Haug Stefan (BT-FIR/MKR-EU BT-FIR/MKA-EU)
Distribution BU IN	<input type="checkbox"/>
Distribution BU ESS	<input checked="" type="checkbox"/> Markus Brack (BT-ESS/MKP2.3), Huse Istvan (BT/PRM2-EU) <input type="checkbox"/> <input type="checkbox"/>
Other parties affected	<input checked="" type="checkbox"/> Schrimpf Felix (BT-ASA/PRM) <input checked="" type="checkbox"/> Proyer Konrad (BT-ASA/SRA-EU), Wilson Jim (BT-ASA/SRA-NA), Tan Woo Khiang (BT-ASA/SRA-AP) <input checked="" type="checkbox"/> Hemke Tobias (BT-ASA/STS3-EU); Gill Manjit (BT-ASA/STS-UK) <input checked="" type="checkbox"/> Teleservice Support (SO/OMM7.3-Mb) <input checked="" type="checkbox"/> Becker Oliver (BT-IE/PRM1) <input checked="" type="checkbox"/> Schwichtenberg Heiko (BT-IE/PRM2) <input type="checkbox"/>