

Technical Information	Date: 04.06.2018 Official: Marier Department: BT-FIR/MKP3
------------------------------	---

Tech. Information No.	2172 / 2018
Subject:	FPA-5000: new firmware 2.21.2 and RPS 4.10.3 release

Short Description:	<ul style="list-style-type: none"> - New feature: display of detectors 10-digit serial number/ID - Fixed: sporadic FNM-420 trouble - See "new features and "solved issues" below for detailed information
---------------------------	--

Hardware <input type="checkbox"/>	<input type="checkbox"/> Device	<input type="checkbox"/> Module	<input type="checkbox"/> PCBA
Software <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Application	<input type="checkbox"/> Driver / Extension	<input checked="" type="checkbox"/> Firmware

Affected Products (details)	CTN	SAP no.	Aff. version	New version
Main Panel Controller	MPC-xxxx-C	all languages	2.20.3	2.21.2
Main Panel Controller	MPC-xxxx-B	all languages	2.20.3	2.21.2
Main Panel Controller	FPA-1200-MPC-C	all languages	2.20.3	2.21.2
Main Panel Controller	FPA-1200-MPC	all languages	2.20.3	2.21.2
Main Panel Controller	FPA-1100-DE	F.01U.316.057	2.20.3	2.21.2
Remote Keypad	FMR-5000-C	all languages	2.20.3	2.21.2
Remote Keypad	FMR-5000	all languages	2.20.3	2.21.2
FPA configuration tool	FSP-5000-RPS	F.01U.005.615	4.9.3	4.10.3

Number of delivered devices		
Period of delivery	from:	to:
Affected serial numbers	from:	to:

Priority Level	Criterion
I <input type="checkbox"/>	The change has to be made immediately (see dates below)
II <input type="checkbox"/>	The change has to be made during the next inspection.
III <input checked="" type="checkbox"/>	Change has to be made, if the error pattern recurs and with new installations.
None <input type="checkbox"/>	General Information (like new tool, new feature, new SW release)

Action Plan	
<input checked="" type="checkbox"/>	Inform customers
<input type="checkbox"/>	Arrange re-work of stock (CSO)
<input type="checkbox"/>	Arrange re-work of stock (customer)
<input type="checkbox"/>	Arrange re-work of installed products
<input type="checkbox"/>	See detailed actions on following pages

Start Date		Completion Date	
-------------------	--	------------------------	--


New Features

Print out of this template is not subject of the updating service. Only the version in the Intranet is always up to date.

1.1. Display printed IDs of detectors in the panel and the RPS software

This feature allows to see the identical ID numbers printed on the detector label also in the panel. Detectors which are now identifiable by its 10 digit ID number, the first two digits are replaced by a XX. This applies to elements with the same type-ID but different type-code.

For RPS the first two digits are always represented as XX.



The screenshot shows the RPS software interface. On the left, a tree view under 'Nodes / Module' shows 'FPA-5000 MPC Type C - 1.1 - RSN 001 - R' expanded, with 'LSN 300 Module - 3 - LSN improved - T' selected. The main window displays a table of LSN devices:

LSN Device	Physical Address	Current ID	Date/Time	Previous ID	Date/Time
3 - FLM-420-NAC ...	3.1.3.0				
11 - FAP-O420/42...	3.1.11.0	XX14000044	24.05.2018 10:29:...	XX04183711	24.05.2018 10:01:...
30 - DM210/SM2...	3.1.30.0				
110 - FLM-420/4...	3.1.110.0				

Below the table, the 'Diagnostics' section shows 'LSN 0300 A' with 'Address 3' and 'Last refresh 24 May 2018 10:35:27'. A table lists the detected device:

No.	Type	Address	ID
1	FAP-O425	4-1	xx14000044

To the right, a physical detector label for 'BOSCH FAD-425-O-R' is shown. It includes a QR code and the following information:

- EN54-7
- EN 54-17: 2005
- VdS: Gxxxxxx
- Mat/N: F01U283067
- ID: 3314000044
- S/N: 093139345304040044
- 1419

1.2. Control of sounders via sets

Now it is possible to trigger the activation of all sounders in a set (output group) via UGM2040 or BIS.

1.3. Automatic reset of transmission path fault of transmission device

In case of a fault of a transmission path of a transmission device, the corresponding trouble does not require a reset if the fault root cause is no longer present. So it disappears automatically if the transmission path(s) is (are) working again.

1.4. Improvements for "Personalized Menu"

- Invoking the Personalized Menu via Remote Terminal is now possible (accessible via Key combination "Home + 3")
- Now allows to trigger action to NACs which are in a set (this applies to user defined sets).

1.5. Detector removal for Hongkong Market

Now it is possible to configure detector removal via FSP-5000-RPS.

Solved Issues

1.1. Random NAC Sounder Trouble

FNM-420-x sounder reported troubles after hours to days even if no trouble cause was present. This error has been fixed within the firmware of the FPA-5000 Panel Controller. No exchange of sounders necessary.

1.2. Transmission device not activated in case of A-C Short

It was not possible to activate a transmission device in case of a continuous activation of the feedback lines for a transmission device (short of A-C). This issue has been solved.

1.3. FPA-5000 USB Driver does not work with most recent Windows 10 version

The USB Driver now works with all versions of Windows 10.

1.4. FAT does not work if more than 12 nodes are in the network

The FAT now works if the number of nodes in the same scope is less or equal to 12.

1.5. Intermediate Alarm Storage of a conventional detector with EOLM

The intermediate alarm storage now works with a conventional detector connected to a FLM-420/4-CON regardless if the conventional line is terminated with an End-Of-Line-Module instead of an End-Of-Line-Resistor.

Problem description**Cause****Action****Notes**

- MPC firmware V2.21.2 is compatible with OPC Server 1.4.2 and 1.4.3 and also FSI-lib 1.4.2 and 1.4.3
- Download all technical bulletins (TIs) and released software from the '[ST-FIR Tech Support](#)' sharepoint

(registered users only)

Required Components	Part no.

Attachment(s)

BU Manager	Knauel	Clerk in Charge:	Marier
-------------------	--------	-------------------------	--------

Distribution

Distribution BU FIR	<input checked="" type="checkbox"/> Julian Tersteegen (BT-FIR/QMM), Claudia Majer (BT-FIR/QMM), Knauel Thomas (BT-FIR/MKP BT-FIR/MKT), Heckl Michael (BT-FIR/MKP3) <input checked="" type="checkbox"/> Angstenberger Josef (BT-FIR/MKR-EU) <input checked="" type="checkbox"/> Ong Kah Seong (BT-FIR/MKR-AP), Leonard Hew (BT-FIR/MKR-AP) <input checked="" type="checkbox"/> Paredes Ivan (BT/MKR-LA), Miers Christopher (BT/FIR-MKT) <input checked="" type="checkbox"/> Haug Stefan (BT-FIR/MKR-EU BT-FIR/MKA-EU)
Distribution BU IN	<input type="checkbox"/>
Distribution BU ESS	<input checked="" type="checkbox"/> Markus Brack (BT-ESS/MKP2.3), Huse Istvan (BT/PRM2-EU) <input type="checkbox"/> <input type="checkbox"/>
Other parties affected	<input checked="" type="checkbox"/> Schrimpf Felix (BT-ASA/PRM) <input checked="" type="checkbox"/> Proyer Konrad (BT-ASA/SRA-EU), Wilson Jim (BT-ASA/SRA-NA), Tan Woo Khiang (BT-ASA/SRA-AP) <input checked="" type="checkbox"/> Hemke Tobias (BT-ASA/STS3-EU); Gill Manjit (BT-ASA/STS-UK) <input checked="" type="checkbox"/> Teleservice Support (SO/OMM7.3-Mb) <input checked="" type="checkbox"/> Becker Oliver (BT-IE/PRM1) <input checked="" type="checkbox"/> Schwichtenberg Heiko (BT-IE/PRM2) <input type="checkbox"/>