

Technical Information	Date: 25.11.2020 Official: Wittmann Department: BT-FIR/MKP
------------------------------	--

Tech. Information No.	2335 / 2020
Subject:	FCS-8000-VFD-B - AVIOTEC video-based fire detection

Short Description:	New firmware 7.72 fixes bug in alarm hold time of 7.70
---------------------------	--

Hardware <input type="checkbox"/>	<input type="checkbox"/> Device	<input type="checkbox"/> Module	<input type="checkbox"/> PCBA
Software <input checked="" type="checkbox"/>	<input type="checkbox"/> Application	<input type="checkbox"/> Driver / Extension	<input checked="" type="checkbox"/> Firmware

Affected Products (details)	CTN	SAP no.	Aff. version	New version
AVIOTEC IP starlight 8000	FCS-8000-VFD-B	F.01U.317.536	7.70.0126	7.72

Number of delivered devices		
Period of delivery	from: 25.08.2020	to:
Affected serial numbers	from: -	to: -

Priority Level	Criterion
I	<input type="checkbox"/> The change has to be made immediately (see dates below)
II	<input type="checkbox"/> The change has to be made during the next inspection.
III	<input checked="" type="checkbox"/> Change has to be made, if the error pattern recurs and with new installations.
None	<input type="checkbox"/> General Information (like new tool, new feature, new SW release)

Action Plan	
<input type="checkbox"/>	Inform customers
<input type="checkbox"/>	Arrange re-work of stock (CSO)
<input type="checkbox"/>	Arrange re-work of stock (customer)
<input type="checkbox"/>	Arrange re-work of installed products
<input checked="" type="checkbox"/>	See detailed actions on following pages

Start Date		Completion Date	
-------------------	--	------------------------	--



<p>Error(s) and Effect(s)</p> <p>Intended alarming behavior: Alarms, regardless the alarm duration, will be held for 10 seconds after the alarm ends.</p> <p>Error description in firmware 7.70: In some cases with high processor load of the camera, short flame alarms were not held for the intended time of 10 seconds. The relay and all other alarming methods like metadata etc. were only triggered during the flame alarm time. Alarms might be missed in installations, where alarms are polled from external devices with a predefined, fix polling timeframe.</p>

<p>Cause</p> <p>:</p>

<p>Action(s)</p> <p>Update firmware immediately to 7.72 Product catalogue - download in video-based fire detection https://resources-boschsecurity-cdn.azureedge.net/public/software/ CPP6_H.264_Firmware__Software_FW_7_72_0008_AVIOTEC_only_al I_80217070731.zip</p>

Required Components	Part no.

<p>Attachment(s)</p>

<p>BU Manager </p>	<p>Clerk in Charge: </p>
--	--

Distribution

Distribution BU FIR Fire Systems	<input checked="" type="checkbox"/> Julian Tersteegen (BT-FIR/QMM), Claudia Majer (BT-FIR/QMM), Knauel Thomas (BT-FIR/MKP BT-FIR/MKT), Heckl Michael (BT-FIR/MKP3) <input checked="" type="checkbox"/> Angstenberger Josef (BT-FIR/MKR-EU) <input checked="" type="checkbox"/> Ong Kah Seong (BT-FIR/MKR-AP), Leonard Hew (BT-FIR/MKR-AP) <input checked="" type="checkbox"/> Paredes Ivan (BT/MKR-LA), Miers Christopher (BT/FIR-MKT) <input checked="" type="checkbox"/> Haug Stefan (BT-FIR/MKR-EU BT-FIR/MKA-EU) <input type="checkbox"/>
Distribution BU SC Intrusion Systems	<input type="checkbox"/> Petricoin Dennis (BT-SC/PAS2 BT-SC/PAS2-MKP), Dobson Roxanne (BT-SC/QMM2), Hupka Peter (BT-SC/PAS2-MKP5), Weissert Thorsten (BT-SC/PAS2-MKP5) <input type="checkbox"/> Kugler Gerhard (BT-SC/MKR6-EU), Berberian Alexandra (BT-SC/MKR-SEF), Shah Dhaval (BT-FIR/MKR-SEM), Gomez Arevalo Olga (BT/SEI-SCM), Malek Michal (BT-SC/MKR-SEP), van den Berg Quintin (BT-SC/MKR-SEZ), Kiselev Grigory (BT-FIR/MKR-SEO), Sonmez Onur (BT-FIR/MKR-SET), Cojocaru Laurentiu (BT-SC/MKR-SEA BT/SEA-SBD2), Riboli Stefano (BT-SC/MKR-SES), El Makhfi Otmane (BT-SC/MKR-SAN), Reuvers Willfried (BT-SC/MKR-SEB), Kuehlewind Uwe (BT-SC/MKR-SEC), Pillai Kiran (BT-SC/MKR-SEU), Karlsson Anders (BT-SC/MKR-SEN) <input type="checkbox"/> Cabral Paula (BT-SC/MKR-LA), Garms Paul (BT-SC/MKR2-NA) <input type="checkbox"/> Premo Mike (BT-SC/PAS2-ENG1), Meichelbeck Markus (BT-SC/PAS2-ENG5) <input type="checkbox"/> Schmidt Michaela (BT/MKW1) <input type="checkbox"/> Klein Alexander (BT/SC-MKI) <input type="checkbox"/>
Other parties affected	<input type="checkbox"/> Schrimpf Felix (BT-ASA/MKP BT-ASA/MKC) <input type="checkbox"/> Proyer Konrad (BT-ASA/SRA-EU BT-ASA/SRA2-EU), Dias Andre (BT-ASA/SRA-LA), Wilson Jim (BT-ASA/SRA-NA), Tan Woo Khiang (BT-ASA/SRA-AP) <input type="checkbox"/> Gill Manjit (BT-ASA/STS-UK) <input type="checkbox"/> Teleservice Support (SO/OMM1.3-MB) <input type="checkbox"/> Becker Oliver (BT-IE/PRM1), Goos Irina (BT-IE/PRM1) <input type="checkbox"/> Adelman Petra (BT-IE/EAP3) <input type="checkbox"/>

