

Technical Information	Date: 06.11.2023 Official: Heckl Department: BT-FS/MKP3
------------------------------	---

Tech. Information No.	2554 / 2023
Subject:	FPP 5000 / Verdrahtungsfehler der Netzleitung

Short Description:	<p>Es wurde an einer abgesetzten Energieversorgung (FPP 5000) ein Verdrahtungsfehler festgestellt. Die Phase L1 (Braun) wurde mit dem Schutzleiter (Grün-gelb) vertauscht. Siehe Bild folgend.</p> <p>Achtung Lebensgefahr: Durch den Verdrahtungsfehler kann am Gehäuse der UPS 2416 A 230V anliegen.</p> <p>Bereits installierte Feldinstallationen sind nicht betroffen.</p>
---------------------------	--

Hardware <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Device	<input checked="" type="checkbox"/> Module	<input type="checkbox"/> PCBA
Software <input type="checkbox"/>	<input type="checkbox"/> Application	<input type="checkbox"/> Driver / Extension	<input type="checkbox"/> Firmware

Affected Products (details)	CTN	SAP no.	Aff. version	New version
External power supply kit	FPP 5000	F.01U.511.307		
Mounting frame for power supply, medium	PMF 0002 A	F.01U.511.306		

Number of delivered devices		
Period of delivery	from:	to:.
Affected serial numbers	from:	to:

Priority Level	Criterion
I	<input type="checkbox"/> The change has to be made immediately (see dates below)
II	<input type="checkbox"/> The change has to be made during the next inspection.
III	<input checked="" type="checkbox"/> Change has to be made, if the error pattern recurs and with new installations .
None	<input type="checkbox"/> General Information (like new tool, new feature, new SW release)

Action Plan	
<input checked="" type="checkbox"/>	Inform customers
<input type="checkbox"/>	Arrange re-work of stock (CSO)
<input checked="" type="checkbox"/>	Arrange re-work of stock (customer)
<input type="checkbox"/>	Arrange re-work of installed products
<input checked="" type="checkbox"/>	See detailed actions on following pages

Print out of this template is not subject of the updating service. Only the version in the Intranet is always up to date.

Start Date	Sofort	Completion Date	
Detailed Actions:			
Bei Neuinstallationen ist die Verdrahtung vor der ersten Inbetriebnahme / vor der ersten unter Spannungsetzung zu überprüfen. Im Falle von vertauschten Adern ist die Verdrahtung zu korrigieren.			

Removed features:

Solved Issues:

Notes:

Required Components	Part no.

Attachment(s)

Print out of this template is not subject of the updating service. Only the version in the Intranet is always up to date.

BU Manager	Thomas Knauel	Clerk in Charge:	Michael Heckl
-------------------	---------------	-------------------------	---------------

Distribution

Distribution BU FIR Fire Systems	<input checked="" type="checkbox"/> Ivan Martinko (BT/QMM-FS), Gerhard Puechler (BT/QMM-FS), Andreas Speich (BT/QMM-FS) <input checked="" type="checkbox"/> Thomas Knauel (BT-FS/MKP BT-FS/PJ-PG), Kristof Vandenberghe (BT-FS/MKP1), Bernd Harbers BT-FS/MKP1) <input checked="" type="checkbox"/> Ron Marier (BT-FS/MKP3), Michael Heckl (BT-FS/MKP3) <input checked="" type="checkbox"/> Josef Angstenberger (BT-FS/MKR-EU), Jakub Bednarz (BT-FS/MKR-EU BT-FS/MKA- EU) <input checked="" type="checkbox"/> Kah Seong Ong (BT-FS/SAM-AP BT-FS/MKR-AP), Leonard Hew (BT-FS/MKR-AP) <input checked="" type="checkbox"/> Renato Lima (BT-FS/MKR-LA), James Mottorn (BT-FS/MKP-AM)
--	---

Other parties affected	<input checked="" type="checkbox"/> Felix Schrimpf (BT-ASA/MKP BT-ASA/MKC) <input checked="" type="checkbox"/> Konrad Proyer (BT-ASA/MSR-Sab), Andre Dias (BT-ASA/SRA-LA), Jim Wilson (BT-ASA/TCR-Lio BT-ASA/MSR2-Lio), Khiang Tan Woo (BT-ASA/SRA-AP) <input checked="" type="checkbox"/> Manjit Gill (BT-ASA/STS2-EU) <input type="checkbox"/> Teleservice Support (SO/OPM8.10Mb) <input checked="" type="checkbox"/> Holger Behrens (BT-IE/SPM-SF) <input checked="" type="checkbox"/> Petra Adelmann (BT-IE/CTA-CSS1) <input checked="" type="checkbox"/> David Ziegler (BT-IE/SPM-SF), Ines Schittenhelm (BT-IE/SPM-SF), Michiel de Graaf (BT-IE/XSP-NL), Jaap Smit (BT-IE/XSP-NL), Productmanagement.sn1@nl.bosch.com (BT-IE/XSP-NL)
---------------------------	---