

Technical Information	Date: 02.06.2015 Official: Marier Department.: ST-FIR/MKP3
------------------------------	--

Tech. Information No.	1928 / 2015
Subject:	New MPC SW release 2.14.7 / RPS 4.3.11

Short Description:	Added feature "Remote Connect" (configuration and maintenance of fire detection system via internet)
---------------------------	--

Hardware <input type="checkbox"/>	<input type="checkbox"/> Device	<input type="checkbox"/> Module	<input type="checkbox"/> PCBA
Software <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Application	<input type="checkbox"/> Driver / Extension	<input checked="" type="checkbox"/> Firmware

Affected Products (details)	CTN	SAP no.	Aff. version	New version
FPA-5000 panel controller	MPC-xxxx-B		2.13.12	2.14.7
FPA-5000 panel controller	MPC-xxxx-C		2.13.12	2.14.7
FPA-1200 panel controller	FPA-1200-MPC		2.13.12	2.14.7
FPA-1200 panel controller	FPA-1200-MPC-C		2.13.12	2.14.7
FMR-5000 keypad	FMR-5000-xx		2.13.12	2.14.7
FMR-5000 keypad	FMR-5000-C		2.13.12	2.14.7
FPA configuration tool	FSP-5000-RPS	F.01U.005.615	4.1.10	4.3.11

Number of delivered devices	
Period of delivery	from: to:
Affected serial numbers	from: to:

Priority Level	Criterion
I <input type="checkbox"/>	The change has to be made immediately (see dates below)
II <input type="checkbox"/>	The change has to be made during the next inspection.
III <input checked="" type="checkbox"/>	Change has to be made, if the error pattern recurs and with new installations.
None <input type="checkbox"/>	General Information (like new tool, new feature, new SW release)

Action Plan	
<input checked="" type="checkbox"/>	Inform customers
<input type="checkbox"/>	Arrange re-work of stock (NSO)
<input type="checkbox"/>	Arrange re-work of stock (customer)
<input type="checkbox"/>	Arrange re-work of installed products
<input type="checkbox"/>	See detailed actions on following pages

Start Date		Completion Date	
-------------------	--	------------------------	--

Error(s) and Effect(s)	
<p>1) New features: Remote internet connection to FPA for full system transparency</p> <p>a) MPC allows configuration and diagnostics of Remote Connect (set Remote ID, connect to server)</p> <p>b) RPS allows to configure and establish Remote Connect (note: direct IP connection not possible anymore)</p> <p>c) IP-infrastructure for EffiLink is given</p> <p>d) Remote Portal established to manage operators, systems and licenses for Remote Connect (F.01U.310.142)</p> <p>e) Secure Network Gateway (F.01U.309.110) introduced to enable Remote Connect</p> <p>2) Defect Fixes (MKS-ID)</p> <p>a) 295923 - Point reported alarm although switched to maintenance mode</p> <p>b) 247072 - RPS 2.9.12 - mpp file name by default "MPPData.mpp"</p> <p>c) 251618 - Ethernet trouble in case of redundant PCtrl and FSI/OPC connection</p> <p>d) 266043 - RPS 2.10.8 ENO/FSE selectable usage types not found under function type mappings</p> <p>e) 175046 - "Enable Call" button does not appear on assigned remote keypad (FMR)</p> <p>f) 294173 - If you copy a label you have to acknowledge that you either accept or discard the label</p> <p>Note: The new firmware MPC V2.14.7 is compatible with FPA-OPC V1.3.4 and FSM5000FSI V1.3.4</p>	
Cause	
Action(s)	
Required Components	Part no.
Attachment(s)	
BU Manager	Knauel
Clerk in Charge:	Marier

Distribution

Distribution BU FIR	<input checked="" type="checkbox"/> Celebi Guenay (ST-FIR/QMM), Knauel Thomas (ST-FIR/MKP ST-FIR/MKT), Heckl Michael (ST-FIR/MKP3) <input checked="" type="checkbox"/> Angstenberger Josef (ST-FIR/MKR-EU) <input checked="" type="checkbox"/> Lim Yong Gang (ST/SRM-AP), Leonard Hew (ST-FIR/MKR-AP), Quek Daniel (ST-CO/MKR2-AP) <input checked="" type="checkbox"/> Squarize Alex (ST/SRM-LA), Pinto Erik (ST/STS-LA ST-ASA/SRA-LA), Render Chelsea (ST/SRM-NA) <input type="checkbox"/>
Distribution BU IN	<input type="checkbox"/> Hossmann Daniela (ST-IN/MKR-EU), Kugler Gerhard (ST-IN/MKR2-EU), Endres Dirk (ST-IN/QMM) <input type="checkbox"/> Berberian Alexandra (ST-IN/MKR-SEF), Ferrao Eduardo (ST-IN/MKR-SEI), Karlsson Mathias (ST-IN/MKR-SEN), Tantry Ananth (ST-IN/MKR-SEM) <input type="checkbox"/> Mechler Tom (ST-IN/MKR-NA) <input type="checkbox"/>
Distribution BU ESS	<input type="checkbox"/> Loh Leon (ST-ESS/MKP1.4), Maier Holger (ST-ESS/MKP1.2), Wings Maarten (ST-ESS/MKP1.3), Redeker Bernd (ST-ESS/QMM), Jan von Rosenstiel (ST-ESS/MKP1.1), Reinhard Bloss (ST-ESS/MKP1) <input type="checkbox"/> Funke Thomas (ST-ESS/ENG) <input type="checkbox"/> Nikolas Mangold-Takao (ST-ESS/MKP1), Jaco Liebetrau (ST-ESS/MKT) <input checked="" type="checkbox"/> Markus Brack (ST-ESS/MKP2.3), Huse Istvan (ST/PRM2-EU), Law Jeffrey (ST/PRM1-AP) <input type="checkbox"/> Gary Deng (ST-PRM-CN), James Judson (ST-IN/MKR-NA) <input type="checkbox"/>
Other parties affected	<input checked="" type="checkbox"/> Steidle Kurt (ST-ASA/PRM1) <input checked="" type="checkbox"/> Proyer Konrad (ST-ASA/SRA-EU), Schrimpf Felix (ST-ASA/PRM), Wilson Jim (ST-ASA/SRA-AM), Tan Woo Khiang (ST/ASA-AP) <input type="checkbox"/> Pedolzky Georg (ST-BT/PRM1) <input type="checkbox"/> <input type="checkbox"/>