

Technical Information	Date: 21.07.2017 Official: Erhard Department: ST-IN/MKA-EU
------------------------------	--

Tech. Information No.	2115 / 2017
Subject:	Modular Alarm Platform 5000

Short Description:	SW-Update MAP5000 RPS for MAP Bundle1.43.3
---------------------------	--

Hardware <input type="checkbox"/>	<input type="checkbox"/> Device	<input type="checkbox"/> Module	<input type="checkbox"/> PCBA
Software <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Application	<input type="checkbox"/> Driver / Extension	<input type="checkbox"/> Firmware

Affected Products (details)	CTN	SAP no.	Aff. version	New version
RPS for MAP			1.21.0.11	1.21.0.24

Number of delivered devices		
Period of delivery	from:	to:
Affected serial numbers	from:	to:

Priority Level	Criterion
I <input type="checkbox"/>	The change has to be made immediately (see dates below)
II <input type="checkbox"/>	The change has to be made during the next inspection.
III <input checked="" type="checkbox"/>	Change has to be made, if the error pattern recurs and with new installations.
None <input type="checkbox"/>	General Information (like new tool, new feature, new SW release)

Action Plan	
<input type="checkbox"/>	Inform customers
<input type="checkbox"/>	Arrange re-work of stock (CSO)
<input type="checkbox"/>	Arrange re-work of stock (customer)
<input type="checkbox"/>	Arrange re-work of installed products
<input checked="" type="checkbox"/>	See detailed actions on following pages

Start Date		Completion Date	
-------------------	--	------------------------	--

Print out of this template is not subject of the updating service. Only the version in the Intranet is always up to date.

Error(s) and Effect(s)

[EN] Opening an existing configuration will cause RPS to crash. This happens only if the configuration contains at least one device Smartkey SE 320 with configured outputs.

[DE] Das Öffnen einer bestehenden Konfiguration führt zum Absturz von RPS. Dies geschieht nur, wenn die Konfiguration mindestens ein Smartkey SE 320 Element mit konfigurierten Ausgängen beinhaltet.

Cause

[EN] Software bug

[DE] Softwarefehler

Action(s)

[EN] Install the new software if the described error pattern occurs. The new release "RPS for MAP" has the same data base version as the previous RPS, means older installations can be configured, existing configurations can still be used.
With this new sw bundle there is no change of firmware on panel side.

[DE] Installieren Sie die neue Software, falls der beschriebene Fehler auftritt. Die neue Version von „RPS for MAP“ hat dieselbe Datenbankversion, als die Vorgängerversion, d.h. ältere Installationen können damit parametrieren werden, bestehende Parametrierungen können weiter verwendet werden.
Mit diesem neuen SW-Bundle gibt es keine Firmwareänderung auf Zentralenseite.

Required Components	Part no.

Attachment(s)

BU Manager	Denzler ST-IN/RBU-EU	Clerk in Charge:	Erhard ST-IN/MKA-EU
-------------------	----------------------	-------------------------	---------------------

Distribution

Distribution BU FIR	<input type="checkbox"/> Celebi Guenay (ST-FIR/QMM), Knauel Thomas (ST-FIR/MKP ST-FIR/MKT), Heckl Michael (ST-FIR/MKP3) <input type="checkbox"/> Angstenberger Josef (ST-FIR/MKR-EU) <input type="checkbox"/> Lim Yong Gang (ST/SRM-AP), Leonard Hew (ST-FIR/MKR-AP), Quek Daniel (ST-CO/MKR2-AP) <input type="checkbox"/> Squarize Alex (ST/SRM-LA), Pinto Erik (ST/STS-LA ST-ASA/SRA-LA), Render Chelsea (ST/SRM-NA) <input type="checkbox"/>
Distribution BU IN	<input checked="" type="checkbox"/> Denzler Daniel (ST-IN/RBU-EU MKP-EU MKA-EU), Martin Diane (ST-IN/QMM), Kachel Roxanne (ST-IN/QMM), Klein Alexander (ST-IN/MKP-EU), Hupka Peter (ST-IN/MKP-EU), Weissert Thorsten (ST-IN/MKP-EU), Clemens Jasper (ST-IN/CLP-EU MKP-EU), Poessnecker Peter (ST-IN/CLP-EU) <input checked="" type="checkbox"/> Stauber Johannes (ST-IN/MKR-EU MKC-EU), Kugler Gerhard (ST-IN/MKR2-EU), Berberian Alexandra (ST-IN/MKR-SEF), Shah Dhaval (ST-FIR/MKR-SEM), Gomez Arevalo Olga (ST-IN/MKR-SEI), Malek Michal (ST-IN/MKR-SEP), Oppab Maria (ST-IN/MKR-SAN) <input type="checkbox"/> Cabral Paula (ST-IN/MKR-LA), Garms Paul (ST-IN/MKR-NA) <input checked="" type="checkbox"/> Borden Scott (ST-IN/ENG-EU), Meichelbeck Markus (ST-IN/ENG-EU) <input type="checkbox"/> Schmidt Michaela (ST-IN/MKW) <input type="checkbox"/>
Distribution BU ESS	<input type="checkbox"/> Tan Boon Chuan (ST-ESS/MKP1.4), Maier Holger (ST-ESS/MKP1.2), Wings Maarten (ST-ESS/MKP1.3), Redeker Bernd (ST-ESS/QMM), Jan von Rosenstiel (ST-ESS/MKP1.1), Jekelius Friederike (ST-ESS/MKP1) <input type="checkbox"/> Funke Thomas (ST-ESS/ENG) <input type="checkbox"/> Nikolas Mangold-Takao (ST-ESS/MKP1), Jaco Liebetau (ST-ESS/MKT) <input type="checkbox"/> Markus Brack (ST-ESS/MKP2.3), Huse Istvan (ST/PRM2-EU) <input type="checkbox"/> Gary Deng (ST-PRM-CN), Roth Christy (ST-IN/MKR-NA), Claude Hochreutiner (ST-ESS/MKR-AP), Mauricio Santos (ST/SPS-LA), Mikhail Zyrianov (ST-ESS/MKR-EU ST-ESS/MKR-SEP) <input type="checkbox"/>
Other parties affected	<input type="checkbox"/> Schrimpf Felix (ST-ASA/PRM) <input type="checkbox"/> Proyer Konrad (ST-ASA/SRA-EU), Pinto Erik (ST-ASA/SRA-LA), Wilson Jim (ST-ASA/SRA-NA), Tan Woo Khiang (ST-ASA/SRA-AP) <input checked="" type="checkbox"/> Hemke Tobias (ST-ASA/STS3-EU); Gill Manjit (ST-ASA/STS-UK) <input checked="" type="checkbox"/> Teleservice Support (SO/OMM7.3-Mb) <input checked="" type="checkbox"/> Pedolzky Georg (ST-IE/PRM1) <input type="checkbox"/> Adelman Petra (ST-IE/EAP3) <input type="checkbox"/>

Print out of this template is not subject of the updating service. Only the version in the Intranet is always up to date.