

<b>Technical Information</b>	Date: 27.09.2018 Official: Erhard Department: BT-SC/PAS2-MKP5
------------------------------	---

<b>Tech. Information No.</b>	2197 / 2018
<b>Subject:</b>	Modular Alarm Platform 5000

<b>Short Description:</b>	Software-Update MAP5000 Bundle 1.44.2
---------------------------	---------------------------------------

<b>Hardware</b> <input type="checkbox"/>	<input type="checkbox"/> Device	<input type="checkbox"/> Module	<input type="checkbox"/> PCBA
<b>Software</b> <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Application	<input type="checkbox"/> Driver / Extension	<input checked="" type="checkbox"/> Firmware

Affected Products (details)	CTN	SAP no.	Aff. version	New version
Main Panel Zentralenmodul	ICP-MAP5000-2	F.01U.245.556	1.4.0112	1.4.0114
Main Panel Zentralenmodul	ICP-MAP5000-COM	F.01U.289.149	1.4.0112	1.4.0114
Main Panel Zentralenmodul	ICP-MAP5000-S	F.01U.296.016	1.4.0112	1.4.0114
Main Panel Zentralenmodul	ICP-MAP5000-SC	F.01U.299.120	1.4.0112	1.4.0114
RPS for MAP	RPS for MAP		1.21.0.66	1.21.0.68

<b>Number of delivered devices</b>		
<b>Period of delivery</b>	from:	to:
<b>Affected serial numbers</b>	from:	to:

Priority Level	Criterion
I <input type="checkbox"/>	The change has to be made <b>immediately</b> (see dates below)
II <input type="checkbox"/>	The change has to be made during the next inspection.
III <input checked="" type="checkbox"/>	Change has to be made, if the error pattern recurs and with new installations.
None <input type="checkbox"/>	General Information (like new tool, new feature, new SW release)

Action Plan	
<input type="checkbox"/>	Inform customers
<input type="checkbox"/>	Arrange re-work of stock (CSO)
<input type="checkbox"/>	Arrange re-work of stock (customer)
<input type="checkbox"/>	Arrange re-work of installed products
<input checked="" type="checkbox"/>	See detailed actions on following pages

<b>Start Date</b>		<b>Completion Date</b>	
-------------------	--	------------------------	--

Print out of this template is not subject of the updating service. Only the version in the Intranet is always up to date.

Error(s) and Effect(s)
<p>[EN] Fixed defects:                      Panel Restart issue:                      In seldom cases, the panel restarts spontaneously. In the history is logged "Restarted due to Power Failure".</p> <p>RPS compatibility issue with older panel versions (bundle 1.44.0 or older):                      Changes in a received configuration are not accepted under certain circumstances, when the configuration is sent back to the panel. Panel status in "View Status" menu says "Running last good configuration".</p> <p>[DE] Behobene Fehler:                      Spontaner Zentralenneustart:                      In seltenen Fällen führt die Zentrale einen Neustart durch. Im Hintergrundspeicher wird „Neustart wegen Netzausfall“ protokolliert.</p> <p>RPS Kompatibilitätsproblem mit älteren Zentralenversionen (Bundle 1.44.0 oder älter):                      Änderungen in einer empfangenen Konfiguration werden unter bestimmten Umständen nicht übernommen, wenn die Konfiguration wieder zurück in die Zentrale gesendet wird. Im Menü "Zustand anzeigen" wird als Zentralenzustand "Letzte brauchbare Konfiguration" angezeigt.</p>

Cause
<p>[EN] Bug Fix</p> <p>[DE] Fehlerbehebung</p>

Action(s)
<p>[EN] Install the firmware in new installations or in existing installations, if one of the described error pattern occurs.</p> <p>The new release "RPS for MAP" is downward compatible, means older installations can be configured, existing configurations can still be used.</p> <p>[DE] Setzen Sie die neue Firmware bei Neuinstallationen und im Fehlerfall ein.</p> <p>Die neue Version des Parametrierprogramms „RPS for MAP“ ist abwärts kompatibel, d.h. ältere Installationen können damit parametrieren werden, bestehende Parametrierungen können weiter verwendet werden.</p>

Required Components	Part no.

Attachment(s)
<p>MAP5000 Installation Manual:</p> <p>[EN] Please find an updated version of the installation manual attached to the system bundle.</p> <p>[DE] Dem System Bundle wurde eine aktualisierte Version des Installationshandbuchs beigelegt.</p>

<b>BU Manager</b>	Petricoin BT-SC/PAS2	<b>Clerk in Charge:</b>	Erhard BT-SC/PAS2-MKP5
-------------------	----------------------	-------------------------	------------------------

**Distribution**

Distribution BU FIR Fire Systems	<input type="checkbox"/> Julian Tersteegen (BT-FIR/QMM), Claudia Majer (BT-FIR/QMM), Knauel Thomas (BT-FIR/MKP BT-FIR/MKT), Heckl Michael (BT-FIR/MKP3) <input type="checkbox"/> Angstenberger Josef (BT-FIR/MKR-EU) <input type="checkbox"/> Ong Kah Seong (BT-FIR/MKR-AP), Leonard Hew (BT-FIR/MKR-AP) <input type="checkbox"/> Paredes Ivan (BT/MKR-LA), Miers Christopher (BT/FIR-MKT) <input type="checkbox"/> Haug Stefan (BT-FIR/MKR-EU BT-FIR/MKA-EU) <input type="checkbox"/>
Distribution BU SC Intrusion Systems	<input checked="" type="checkbox"/> Petricoin Dennis (BT-SC/PAS2 BT-SC/PAS2-MKP), Dobson Roxanne (BT-SC/QMM2), Hupka Peter (BT-SC/PAS2-MKP5), Weissert Thorsten (BT-SC/PAS2-MKP5) <input checked="" type="checkbox"/> Kugler Gerhard (BT-SC/MKR6-EU), Berberian Alexandra (BT-SC/MKR-SEF), Shah Dhaval (BT-FIR/MKR-SEM), Mendoza Colado Enrique (BT-SC/MKR-SEI), Malek Michal (BT-SC/MKR-SEP), van den Berg Quintin (BT-SC/MKR-SEZ), Kiselev Grigory (BT-FIR/MKR-SEO), Sonmez Onur (BT-FIR/MKR-SET), Cojocarui Laurentiu (BT-SC/MKR-SEA BT/SEA-SBD2), Riboli Stefano (BT-SC/MKR-SES), El Makhfi Otmane (BT-SC/MKR-SAN), Reuvers Willfried (BT-SC/MKR-SEB), Kuehlewind Uwe (BT-SC/MKR-SEC), Pillai Kiran (BT-SC/MKR-SEU), Karlsson Anders (BT-SC/MKR-SEN) <input type="checkbox"/> Cabral Paula (BT-SC/MKR-LA), Garms Paul (BT-SC/MKR1-NA) <input checked="" type="checkbox"/> Premo Mike (BT-SC/PAS2-ENG1), Meichelbeck Markus (BT-SC/PAS2-ENG5) <input type="checkbox"/> Schmidt Michaela (BT/MKW1) <input type="checkbox"/> <input type="checkbox"/>
Other parties affected	<input type="checkbox"/> Schrimpf Felix (BT-ASA/MKP BT-ASA/MKC) <input type="checkbox"/> Proyer Konrad (BT-ASA/SRA-EU BT-ASA/SRA2-EU), Dias Andre (BT-ASA/SRA-LA), Wilson Jim (BT-ASA/SRA-NA), Tan Woo Khiang (BT-ASA/SRA-AP) <input checked="" type="checkbox"/> Gill Manjit (BT-ASA/STS-UK) <input checked="" type="checkbox"/> Teleservice Support (SO/OMM1.3-MB) <input checked="" type="checkbox"/> Becker Oliver (BT-IE/PRM1), Goos Irina (BT-IE/PRM1) <input type="checkbox"/> Adelman Petra (BT-IE/EAP3) <input type="checkbox"/>