

<b>Technical Information</b>	Date: 06.12.2019 Official: Marier Department: BT-FIR/MKP3
------------------------------	---

<b>Tech. Information No.</b>	2265 / 2019
<b>Subject:</b>	FSM-2500/5000: Security Notes

<b>Short Description:</b>	
---------------------------	--

<b>Hardware</b> <input type="checkbox"/>	<input type="checkbox"/> Device	<input type="checkbox"/> Module	<input type="checkbox"/> PCBA
<b>Software</b> <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Application	<input type="checkbox"/> Driver / Extension	<input type="checkbox"/> Firmware

Affected Products (details)	CTN	SAP no.	Aff. version	New version
Fire Monitoring System	FSM-2500/5000	All languages	All versions	--

<b>Number of delivered devices</b>	
<b>Period of delivery</b>	from: to:
<b>Affected serial numbers</b>	from: to:

Priority Level	Criterion
I <input type="checkbox"/>	The change has to be made <b>immediately</b> (see dates below)
II <input type="checkbox"/>	The change has to be made during the next inspection.
III <input checked="" type="checkbox"/>	Change has to be made, if the error pattern recurs and with new installations.
None <input type="checkbox"/>	General Information (like new tool, new feature, new SW release)

Action Plan	
<input checked="" type="checkbox"/>	Inform customers
<input type="checkbox"/>	Arrange re-work of stock (CSO)
<input type="checkbox"/>	Arrange re-work of stock (customer)
<input type="checkbox"/>	Arrange re-work of installed products
<input checked="" type="checkbox"/>	See detailed actions on following pages

<b>Start Date</b>		<b>Completion Date</b>	
-------------------	--	------------------------	--

<b>New Features</b>
---------------------

- |  |
|--|
| <ul style="list-style-type: none"> <li>• None</li> </ul> |
|--|

<b>Solved Issues</b>
----------------------

- |  |
|--|
| <ul style="list-style-type: none"> <li>• None</li> </ul> |
|--|

<b>Notes</b>
--------------

**Security notes:**
**1. Company network**

It is recommended that the workstation used to install FSM server shall not be logged onto a company network – neither before nor during or after installation.  
It is a recommended practice to disable the ability of the Windows operating system to cache credentials on any device where credentials are not needed. Evaluate your servers and workstations to determine the requirements.

**2. MSSQL Express**

The default “sa” password used during installation of the SQL express database shall be changed. It is very important to choose a strong password for the “sa” login.  
In the attachment there is a suggested procedure for changing Sql Server Administrator password.

- Download all technical bulletins (TIs) and released software from the [‘ST-FIR Tech Support’](#) sharepoint (registered users only)

Required Components	Part no.

<b>Attachment(s)</b>
----------------------

TI_2265_2019_ChangePassword_sa.pdf
------------------------------------

<b>BU Manager</b>	Knauel	<b>Clerk in Charge:</b>	Marier
-------------------	--------	-------------------------	--------

**Distribution**

Distribution BU FIR Fire Systems	<input checked="" type="checkbox"/> Julian Tersteegen (BT-FIR/QMM), Claudia Majer (BT-FIR/QMM), Knauer Thomas (BT-FIR/MKP BT-FIR/MKT), Heckl Michael (BT-FIR/MKP3) <input checked="" type="checkbox"/> Angstenberger Josef (BT-FIR/MKR-EU) <input checked="" type="checkbox"/> Ong Kah Seong (BT-FIR/MKR-AP), Leonard Hew (BT-FIR/MKR-AP) <input checked="" type="checkbox"/> Paredes Ivan (BT/MKR-LA), Miers Christopher (BT/FIR-MKT) <input checked="" type="checkbox"/> Haug Stefan (BT-FIR/MKR-EU BT-FIR/MKA-EU) <input type="checkbox"/>
Distribution BU SC Intrusion Systems	<input type="checkbox"/> Petricoin Dennis (BT-SC/PAS2 BT-SC/PAS2-MKP), Dobson Roxanne (BT-SC/QMM2), Hupka Peter (BT-SC/PAS2-MKP5), Weissert Thorsten (BT-SC/PAS2-MKP5) <input type="checkbox"/> Kugler Gerhard (BT-SC/MKR6-EU), Berberian Alexandra (BT-SC/MKR-SEF), Shah Dhaval (BT-FIR/MKR-SEM), Gomez Arevalo Olga (BT/SEI-SCM), Malek Michal (BT-SC/MKR-SEP), van den Berg Quintin (BT-SC/MKR-SEZ), Kiselev Grigory (BT-FIR/MKR-SEO), Sonmez Onur (BT-FIR/MKR-SET), Cojocaru Laurentiu (BT-SC/MKR-SEA BT/SEA-SBD2), Riboli Stefano (BT-SC/MKR-SES), El Makhfi Otmane (BT-SC/MKR-SAN), Reuvers Willfried (BT-SC/MKR-SEB), Kuehlewind Uwe (BT-SC/MKR-SEC), Pillai Kiran (BT-SC/MKR-SEU), Karlsson Anders (BT-SC/MKR-SEN) <input type="checkbox"/> Cabral Paula (BT-SC/MKR-LA), Garms Paul (BT-SC/MKR2-NA) <input type="checkbox"/> Premo Mike (BT-SC/PAS2-ENG1), Meichelbeck Markus (BT-SC/PAS2-ENG5) <input type="checkbox"/> Schmidt Michaela (BT/MKW1) <input type="checkbox"/> Klein Alexander (BT/SC-MKI) <input type="checkbox"/>
Other parties affected	<input checked="" type="checkbox"/> Schrimpf Felix (BT-ASA/MKP BT-ASA/MKC) <input checked="" type="checkbox"/> Proyer Konrad (BT-ASA/SRA-EU BT-ASA/SRA2-EU), Dias Andre (BT-ASA/SRA-LA), Wilson Jim (BT-ASA/SRA-NA), Tan Woo Khiang (BT-ASA/SRA-AP) <input checked="" type="checkbox"/> Gill Manjit (BT-ASA/STS-UK) <input checked="" type="checkbox"/> Teleservice Support (SO/OMM1.3-MB) <input checked="" type="checkbox"/> Becker Oliver (BT-IE/PRM1), Goos Irina (BT-IE/PRM1) <input checked="" type="checkbox"/> Adelmann Petra (BT-IE/EAP3) <input type="checkbox"/>