# TI 2481 / 2022 Panel Firmware Compatibility

Kristof Vandenberghe, BT-FIR/MKP1, 2022-12-09



### Panel Firmware Compatibility New AVENAR panel & keypad hardware

- Introduction of new hardware version 0-009-016
- Successor for initial hardware version 0
- Depending on the version number, a hardware is suitable for certain firmware versions:

Firmware version	Hardware version	
	0	0-009-016
V3.1 – V3.4	✓	
V3.5 and higher	✓	✓
V4.0 - V4.1	✓	
V4.2 and higher	✓	<b>✓</b>


Compatibility overview

- Check chapter 5.2 of AVENAR System manual version 6 (2022-12) for more detailed information
- In general, we always recommend to use the latest firmware version




## Panel Firmware Compatibility Identify Hardware Version

Home -> Diagnostics -> Panel passport




Press Bosch logo for Contact information





#### Panel Firmware Compatibility FSP-5000-RPS Firmware check

- Before downloading the firmware,
   FSP-5000-RPS provides a list of compatible hardware versions suitable for the targeted firmware version
- In case the firmware is not compatible with the hardware, the download of the firmware will not succeed
- When not succeeded, upgrade your controller with the latest available firmware version




FSP-5000-RPS Firmware check



#### Panel Firmware Compatibility Practical Example 1: Installed Base AVENAR


- New AVENAR keypad added to the network
- Not possible to download firmware version 4.1.1





#### Panel Firmware Compatibility Practical Example 1: Installed Base AVENAR


- New AVENAR keypad added to the network
- Upgrade all nodes to firmware version 4.2.0
- Released: December 2022





### Panel Firmware Compatibility Practical Example 2: Installed Base AVENAR & FPA/FMR

New AVENAR panel added to the network





### Panel Firmware Compatibility Practical Example 2: Installed Base AVENAR & FPA/FMR

New AVENAR panel added to the network

