

# Technical Information 2473/2022

## Modular Alarm Plattform 5000

### Short Description

MAP Control Center Firmware

HARDWARE

Device

Module

PCBA

SOFTWARE

Application

Driver / Extension

Firmware

Affected Products (details)	CTN	SAP-no.	Aff. version	New version
MAP Control Center	IUI-MAP0001-2	F.01U.245.556	1.3.9150	1.3.9160 (blue)
				1.4.1020 (white)

### Number of delivered devices

Period of delivery

From: -

To: -

Affected serial numbers

From: -

To: -

### PRIORITY LEVEL

### CRITERION

I	<input type="checkbox"/>	The change must be made <b>immediately</b> (see dates below)
II	<input type="checkbox"/>	The change must be made during the next inspection.
III	<input type="checkbox"/>	Change must be made if the error pattern recurs and with new installations.
NONE	<input checked="" type="checkbox"/>	General Information (like new tool, new feature, new SW / FW release)

## Error(s) and Effect(s)

[EN] New / changed features:

- **MAP Control Center – Firmware (blue GUI)**


The new blue GUI FW support now Ukrainian language

Ukrainian language can only be added or changed in the keypad user settings (RPS for MAP support will follow in the next SW bundle)

- **MAP Control Center – Firmware (white GUI)**

In addition to the Ukrainian language support (see above), we are happy to announce the new MAP Control Center modern Graphical User Interface (GUI)

The already existing excellent menu structure also applies to the new GUI



- **Compatibility**

The new firmware versions 1.3.9160 and 1.4.1020 are backward compatible and can be used on all Control Center.

[DE] Neue / geänderte Leistungsmerkmale:

- **MAP Bedienteil – Firmware (blaues GUI)**

Die neue blaue GUI Firmware unterstützt jetzt die Ukrainische Sprache.

Die Ukrainische Sprache kann derzeit nur in den Bedienteil Benutzereinstellungen hinzugefügt oder geändert werden.

RPS für MAP unterstützt dies ab dem nächsten Softwarebundle.

- **MAP Bedienteil – Firmware (weißes GUI)**

Zusätzlich zur Ukrainischen Sprache (siehe oben) freuen wir uns, dass MAP Bedienteil in einem modernen Graphical User Interface (GUI) ankündigen zu können.

Die bereits existierende und exzellente Menüstruktur gilt auch für das neue GUI.



- **Kompatibilität**

Die neue Firmware Versionen 1.3.9160 und 1.4.1020 sind rückwärtskompatibel und können an allen Bedienteilen genutzt werden.

## Cause

[EN] New MAP Control Center / Keypad firmware

[DE] Neue Bedienteil Firmware

## Action(s)

[EN] Install the firmware in new or in existing installations.

[DE] Setzen Sie die neue Firmware bei Neu.- oder in existierende Installation ein.

## Required Components

## Part no.

-

-

## Attachement(s)

BU Manager	Clerk in Charge
Schlechtriem (BT-AI/GP BT-AI/SA BT-AI/PAI)	Schröder (BT-AI/PAI-MKP5)

Distribution

Distribution BU AI Intrusion Systems	<input checked="" type="checkbox"/> Schlechtriem Gregor (BT-AI/GP BT-AI/SA BT-AI/PAI) <input checked="" type="checkbox"/> Steeman Wilfred (BT-AI/SAL2 BT-AI/SAL2-EU) <input checked="" type="checkbox"/> Kubilay Sevil (BT-AI/SAL2-EU) <input checked="" type="checkbox"/> Meichelbeck Markus (BT-AI/PAI-ENG4) <input checked="" type="checkbox"/> Remigio Ana Rita (BT/MKW4) <input checked="" type="checkbox"/> Hupka Peter (BT-AI/PAI-MKP5), Späck Andreas (BT-AI/PAI-MKP5) <input type="checkbox"/>
Other parties affected	<input checked="" type="checkbox"/> Huse Istvan (BT-VS/MKK1), Doll Karl-Heinz (BT-AI/PAA-MKP1) <input checked="" type="checkbox"/> Gill Manjit (BT-ASA/STS2-EU) <input checked="" type="checkbox"/> Teleservice Support (SO/OPM8.10-MB) <input checked="" type="checkbox"/> Winter Oliver (BT-IE/PRM-SR BT-IE/PRM1-SR), Kennouche David (BT-IE/PRM2-SR) <input type="checkbox"/>