

Technical Information	Date: 03.05.2021 Official: Marier Department: BT-FIR/MKP3
------------------------------	---

Tech. Information No.	2363 / 2021
Subject:	Smart Safety Link to PRAESENSA

Short Description:	Use relay contacts to interface with PRAESENSA voice alarm systems
---------------------------	--

Hardware <input checked="" type="checkbox"/>	<input type="checkbox"/> Device	<input type="checkbox"/> Module	<input type="checkbox"/> PCBA
Software <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Application	<input type="checkbox"/> Driver / Extension	<input type="checkbox"/> Firmware

Affected Products (details)	CTN	SAP no.	Aff. version	New version
PRAESENSA	PRA-SCL	F.01U.325.042	n.a.	n.a.
AVENAR panel 8000	FPE-8000-PPC	F.01U.352.441	n.a.	n.a.
AVENAR panel 2000	FPE-2000-PPC	F.01U.352.443	n.a.	n.a.
FPA-5000	MPC-XXXX-C	F.01U.169.501	n.a.	n.a.
	MPC-XXXX-B	F.01U.074.867	n.a.	n.a.
FPA-1200	FPA-1200-MPC-C	F.01U.169.502	n.a.	n.a.
	FPA-1200-MPC	F.01U.090.045	n.a.	n.a.

Number of delivered devices	n.a.
Period of delivery	from: n.a. to: n.a.
Affected serial numbers	from: n.a. to: n.a.

Priority Level	Criterion
I <input type="checkbox"/>	The change has to be made immediately (see dates below)
II <input type="checkbox"/>	The change has to be made during the next inspection.
III <input checked="" type="checkbox"/>	Change has to be made, if the error pattern recurs and with new installations.
None <input type="checkbox"/>	General Information (like new tool, new feature, new SW release)

Action Plan	
<input checked="" type="checkbox"/>	Inform customers
<input type="checkbox"/>	Arrange re-work of stock (CSO)
<input type="checkbox"/>	Arrange re-work of stock (customer)
<input type="checkbox"/>	Arrange re-work of installed products
<input type="checkbox"/>	See detailed actions on following pages

Start Date		Completion Date	
New Features:			

Removed features:**Solved Issues:****Notes:**

Use relay contacts to interface FPA and AVENAR fire panels with PRAESENSA voice alarm systems.

An Ethernet connection between a fire panel and PRAESENSA can currently disrupt the functional behavior and may lead to fire alarms that are not transmitted.

Smart Safety Link to PRAESENSA is currently scheduled to be released by 09/2021.

Smart Safety Link to Praesideo, PAVIRO and Plena voice alarm systems are released solutions and still allowed to be installed in the field.

Required Components	Part no.

Attachment(s)**BU Manager**

Thomas Knauel

Clerk in Charge:

Ron Marier

Distribution

Distribution BU FIR Fire Systems	<input checked="" type="checkbox"/> Julian Tersteegen (BT-FIR/QMM), Claudia Majer (BT-FIR/QMM), Knauel Thomas (BT-FIR/MKP BT-FIR/MKT), Heckl Michael (BT-FIR/MKP3) <input checked="" type="checkbox"/> Angstenberger Josef (BT-FIR/MKR-EU) <input checked="" type="checkbox"/> Ong Kah Seong (BT-FIR/MKR-AP), Leonard Hew (BT-FIR/MKR-AP) <input checked="" type="checkbox"/> Paredes Ivan (BT/MKR-LA), Miers Christopher (BT/FIR-MKT) <input checked="" type="checkbox"/> Haug Stefan (BT-FIR/MKR-EU BT-FIR/MKA-EU) <input type="checkbox"/>
Distribution BU SC Intrusion Systems	<input type="checkbox"/> Petricoin Dennis (BT-SC/PAS2 BT-SC/PAS2-MKP), Dobson Roxanne (BT-SC/QMM2), Hupka Peter (BT-SC/PAS2-MKP5), Weissert Thorsten (BT-SC/PAS2-MKP5) <input type="checkbox"/> Kugler Gerhard (BT-SC/MKR6-EU), Berberian Alexandra (BT-SC/MKR-SEF), Shah Dhaval (BT-FIR/MKR-SEM), Gomez Arevalo Olga (BT/SEI-SCM), Malek Michal (BT-SC/MKR-SEP), van den Berg Quintin (BT-SC/MKR-SEZ), Kiselev Grigory (BT-FIR/MKR-SEO), Sonmez Onur (BT-FIR/MKR-SET), Cojocaru Laurentiu (BT-SC/MKR-SEA BT/SEA-SBD2), Riboli Stefano (BT-SC/MKR-SES), El Makhfi Otmane (BT-SC/MKR-SAN), Reuvers Willfried (BT-SC/MKR-SEB), Kuehlewind Uwe (BT-SC/MKR-SEC), Pillai Kiran (BT-SC/MKR-SEU), Karlsson Anders (BT-SC/MKR-SEN) <input type="checkbox"/> Cabral Paula (BT-SC/MKR-LA), Garms Paul (BT-SC/MKR2-NA) <input type="checkbox"/> Premo Mike (BT-SC/PAS2-ENG1), Meichelbeck Markus (BT-SC/PAS2-ENG5) <input type="checkbox"/> Schmidt Michaela (BT/MKW1) <input type="checkbox"/> Klein Alexander (BT/SC-MKI) <input type="checkbox"/>
Other parties affected	<input checked="" type="checkbox"/> Schrimpf Felix (BT-ASA/MKP BT-ASA/MKC) <input checked="" type="checkbox"/> Proyer Konrad (BT-ASA/SRA-EU BT-ASA/SRA2-EU), Dias Andre (BT-ASA/SRA-LA), Wilson Jim (BT-ASA/SRA-NA), Tan Woo Khiang (BT-ASA/SRA-AP) <input checked="" type="checkbox"/> Gill Manjit (BT-ASA/STS-UK) <input checked="" type="checkbox"/> Teleservice Support (SO/OMM1.3-MB) <input checked="" type="checkbox"/> Heiko Schwichtenberg (BT-IE/PRM-SF) <input checked="" type="checkbox"/> Adelman Petra (BT-IE/EAP3) <input checked="" type="checkbox"/> Philipp Pauly (BT-IE/PRM-SF)