

# Technical Bulletin

## MAP 5000 main panels

### Downgrade

Issue severity	Products affected
<input type="checkbox"/> High. Act immediately	▶ ICP-MAP5000-2
<input checked="" type="checkbox"/> Medium. Bosch Security Systems strongly recommends you take the action described below.	▶ ICP-MAP5000-COM
<input type="checkbox"/> Low. Advisory	▶ ICP-MAP5000-S
	▶ ICP-MAP5000-SC

**Oct 28, 2022**

#### Issue

[EN]

ICP-MAP5000 main panels with firmware version 1.4.0204 or 1.4.0212 must be downgraded.

[DE]

ICP-MAP5000 Zentralenmodule mit Firmware Version 1.4.0204 oder 1.4.0212 müssen mittels eines Downgrades auf Firmware Version 1.4.0176 gesetzt werden.

#### Resolution


[EN]

To prevent bricked panels, you must downgrade the main panels to firmware version **1.4.0176** before initial installation.

- Use RPS for MAP version 1.22.0.107 or higher for downgrading.
- Download RPS for MAP from MAP5000 Certified Partner Portal.

Downgrade of Bosch Data Bus (BDB) components (LSN Gateway, Power supply, DE module, Keypad) is not needed.

Additional label with Downgrade information on affected products, will be placed on the box:

	<b>BOSCH</b>
<b>Downgrade to FW 1.4.0176 required!</b> RPS for MAP version ≥ 1.22.0.107 for downgrade needed For details, please refer to Technical Bulletin in the MAP5000 Partner Portal	
<b>Downgrade auf FW 1.4.0176 notwendig!</b> RPS für MAP Version ≥ 1.22.0.107 für Downgrade benötigt Für Details, siehe Technical Bulletin im MAP5000 Partner Portal	


[DE]

Um "bricked Panels" zu vermeiden, muss ein Downgrade des Zentralenmoduls auf die Firmware Version 1.4.0176, noch vor der Erstkonfiguration, erfolgen.

- Für das Downgrade ist die RPS für MAP Version 1.22.0.107 oder höher zu verwenden.
- RPS für MAP ist im MAP5000 Certified Partner Portal als Download verfügbar.

Ein Downgrade der Bosch Data Bus (BDB) Komponenten (LSN Gateway, Power Supply, Bedienteil) ist nicht nötig.

Ein zusätzlicher Hinweis wird auf der Verpackung der betroffenen Produkte aufgebracht:



**Bosch Security Systems B.V.**

Torenallee 49

5617 BA Eindhoven

Netherlands

**[www.boschsecurity.com](http://www.boschsecurity.com)**

© Bosch Security Systems B.V., 2022